

Dart Aerospace Ltd. 1270 Aberdeen St Hawkesbury, ON K6A 1K7 Canada

ENGINEERING CHANGE REQUEST

Tailor, Ketan

Lee, Michael

Provencal, Chris

Drouin, Steven

Drouin, Steven

Drouin, Steven

Tailor, Ketan

Tel (613) 632-5200 Fax 613 632-5246

ECR 321

Requested By:

DE Approver*:

ECR Specialist:

Requester*:

ECR Lead*:

DM:

Program Manager:

Responsible Engineer: Tailor, Ketan

11/11/21 4:43 PM **Date Opened:**

Tooling/DSK/GSE Drawing Change Type:

Priority: Medium

Quality Disposition Status:

Reason: A revision to the TP-650.5300-1 test plan requires

updates to the vibration test setup. DSK 197 Rev. B -1: Added holes to install the DSK 199-043 clamp support DSK 198 Rev. C -3: Added threaded holes to install the DSK 199-043 clamp support DSK 199 Rev. B Added -043, -9, and -11 dash numbers. The -043 is a weldment of the -9 and -11. The -043 is a "gusset" used to support the DSK 197-1 bottom clamp during the vibration test. -1 and -7: changed a hole into a slot. This

slot is to allow the parts to be installed onto the

vibration test bed.

Expense:

Target Date: **Execution Date: ECR Approval No:**

RE (R&D):

Status Note:

**BRIEF

CONTENT**:

DESCRIPTION:** DESCRIPTION/ ADR DSK Revisions for TP-650.5300-1 Vibration Test

This ECR has been created to release the following drawings: DSK 197 Rev. B DSK 198

Rev. C DSK 199 Rev. B

CUSTOMER APPROVALS

Customer	Customer Visible	Customer Approval Required	*	Customer Approved
		PARTS		

	PARIS						
Part No	Rev	Part Status	Name	Туре	Customer Part	Special Comments	Documents
DSK 199-041		Under Review	Reservoir Assembly Mount	Finished Good			DSK 199
DSK 199-1		Under Review	Base Plate	Sub- assembly			DSK 199
DSK 199-3		Under Review	Support	Sub- assembly			DSK 199
DSK 199-5		Under Review	Mounting Plate	Sub- assembly			DSK 199
DSK 199-7		Under Review	Junction Box Mount	Sub- assembly			DSK 199
DSK197- 1		Under Review	Bottom Clamp	Sub- assembly	DSK197-1		DSK197-RevA.PDF
DSK197- 3		Under Review	Top Clamp	Sub- assembly	DSK197-3		DSK197-RevA.PDF
DSK198- 1		Under Review	ELECTRICAL MECHANICAL VALVE BASE PLATE	Sub- assembly	DSK198-1		DSK198-RevB.pdf
DSK198- 3		Under Review	ELECTRICAL VALVE BASE PLATE	Sub- assembly	DSK198-3		DSK198-RevB.pdf
				NVENTO	RY DISPOSITION	ON	

Part No Revision	Material No	Current Inventory Qty	Purchasing On	-Order Qty	Qty Scheduled for Production
DSK 199-041		2 *	0 *		0 *
DSK 199-1		0 *	0 *		0 *
DSK 199-3		0 *	0 *		0 *
DSK 199-5		0 *	0 *		0 *
DSK 199-7		1 *	0 *		0 *
DSK197-1		5 *	0 *		0 *
DSK197-3		5 *	0 *		0 *
DSK198-1		1 *	0 *		0 *
DSK198-3		1 *	0 *		0 *
		E	FFECTS		•
	ļ	Effect Group			Effects
1. Quarantine?				Immediate quarantine required	
2. ECR Lead Assessment - Impacted Docs & Output				Drawing Change Required	
3. ECR Lead Assessment - Status During ECR				Active - No Under Review	
4. Production Type				In-house production	
5A. ECR Lead Assessment - MINOR Changes				Correction of drawing errors	